


# METHOD OF FUNNEL TYPE PLATE EARTHING



NOTE:  
BOLT NUT, CHECKNUT & WASHERS  
TO BE OF C.I. PLATE & TINNED BRASS  
FOR COPPER PLATE.

IT, CHECK NUT & WASHERS SHOULD BE OF G.I. FOR C.I. PLATE & TINNED BRASS FOR COPPER PLATE.

DRAWING IS NOT TO SCALE

ELECTRICAL CIRCLE

R. & B. DEPTT. GANDHINAGAR