SL No	Category No. & Description	ABB Drg./CLW Drg./ Specn. No.	C&D NO.	QTY./C&D			UNIT	QTY./LOCO			Stock No.	U.L./P.L No.	User shop	REMARKS
				G/9HC	P/7	P/5		G/9HC	P/7	P/5				
29	**R/9/0027 WIND SCREEN ASSY.**	CLW/MS/3/027 Alt.-6					03	1 Set			T307/195	29170291	16	Note: 1) REVISED PURCHASE QUANTITY- Purchase quantity to be calculated by subtracting the quantity of loco shells in category no- R/9/0130 & R/11/0130. 2)Requirement of 5% mfg.spare of wind screen Assly vide note no ELDD/3640/AKM dt.05.01.11 w.e.f 2011-12
	Wind Sereen Assy.	1209-08.130-263 Alt-3	T307/195 B307/266	4 .	4 .	. 4	1	4	4	4				
A. Stage Inspection Required(Yes/No) :- NO														
B.No. of stages with description of each stage(NA/1/2/3) :- NA														
C.Warranty period(in months) from date of delivery :- As per IRS Condition														