

Annexure'A".

Detailed configuration as under

1.	AC/DC clamp meter cum multi meter for précis low current measurements which can be used both as a clamp meter & a multi meter for measuring following parameter			
	Function	Range	Resolution	Display example
	AC(A)	300mA	0.1mA	300.1mA
		3A	0.001A	3.001A
		20A	0.01A	20.01A
	DC(A)	300mA	0.1mA	300.1mA
		3A	0.001A	3.001A
		10A	0.01A	10.01A
	AC(V)	50V	0.01V	50.01V
		300V	0.1V	300.1V
	DC(V)	50V	0.01V	50.01V
		300V	0.1V	300.1V
	Resistance	500 Ohm	0.1 Ohm	500 Ohm
		5k Ohm	1 Ohm	5000 Ohm
		50k Ohm	10 Ohm	5000k Ohm
		500k Ohm	100 Ohm	500.0k Ohm
	Continuity Buzzer sound below < 100 Ohm. Display count 5000			


24.6.22
Sr DSTE/MB