

## Annexure-F

[illegible]

REPAIR CHARGES OF SUB ASSEMBLIES OF DEUTZ ENGINES AT KOLKATA/PUNE { MODEL NO. TCD2015V08PCTM & UNIMAT MACHINE} for Year 2027-28										Offered rate for the year			
Sr.No	Description	HSN Code	Total Req Qty for Model No. TCD2015V08				Basic Rate (2027-28)	GST %	Total Rate including GST (2027-28)	-	-	2027-28	GST in %
1	Fuel Pump	998719	1	-	-	-	-	-	-	-	-		
2	Injectors		8	-	-	-	-	-	-	-	-		
3	Cylinder Head		8	-	-	-	6,429.00	18	60,689.76	-	-		
4	Turbo Charger		1	-	-	-	25,754.00	18	30,389.72	-	-		
5	Air Compressor		1	-	-	-	32,126.00	18	37,908.68	-	-		
6	Major Overhaul of Engine at Pune. The Commissioning of Engine shall be done at site as per daily charges Stipulated in AMC.		2	-	-	-	157,305.00	18	371,239.80	-	-		
7	Crankshaft Grinding Charges at Pune		1	-	-	-	32,126.00	18	37,908.68	-	-		
8	Engine Block		1	-	-	-	106,431.00	18	125,588.58	-	-		
9	Connecting Rod		8	-	-	-	3,175.00	18	29,972.00	-	-		
10	Transportation of Complete Engine From Railway Site to Pune for Overhaul and Back.			-	-	-	Actuals			-	-		
11	Inspection Charges for Engine. If Not Overhauled at Pune.		2	-	-	-	63,462.00	18	149,770.32	-	-		
12	Engine Load Testing Charges		2	-	-	-	238,032.00	18	561,755.52	-	-		
<b>Total Amount</b>									<b>1,405,223.06</b>				