

HYDERABAD DIVISION


SC- MUE SECTION


DETAILED LOCATIONS FOR TFTR-TOE BANK 2026-27

SL No	SSE/PW/	Block Section	From Km	To Km	Net Km	Cum
1	NZB	DHP-NZB	466.400	471.400	5.000	317030
2		UPW-SCP	499.000	500.000	1.000	
3		KMC-UPW	505.000	510.000	5.000	
4		TMD YD	521.000	521.500	0.500	
5		TMD-BKU	524.600	526.300	1.700	
6		TMD-BKU	529.200	529.800	0.600	
				Total	13.800	

Cess Repair work with a quantity of 135870 Cum earth should be carried out at the low cess locations, under ADEN/NZB jurisdiction

The TFTR-Toe bank work and the Cess Repair works should be carried out on Non-Doubling side of the track under ADEN/NZB jurisdiction


 11/6/2026
 DEN/North/HYB


 SSE/eng/HYB