



PLAN OF CHECK DAM





CROSS SECTION OF CHECK DAM

CROSS SECTION OF CHECK DAM




CROSS SECTION OF PROTECTION WALL

	NAME OF WORK Construction of Check Dam and Protection Wall	LEGEND Catchment Area Tank Area Main Canal Peripheral Band Black Gate	TITLE Check Dam and Protection Wall	DATE 10/08/2023	DRAWN BY 10/08/2023	CHECKED BY 10/08/2023	APPROVED BY 10/08/2023	CLIENT M/S. SRI LANKA ENGINEERING CONSULTANTS 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
	NAME OF WORK Construction of Check Dam and Protection Wall	LEGEND Catchment Area Tank Area Main Canal Peripheral Band Black Gate	TITLE Check Dam and Protection Wall	DATE 10/08/2023	DRAWN BY 10/08/2023	CHECKED BY 10/08/2023	APPROVED BY 10/08/2023	CLIENT M/S. SRI LANKA ENGINEERING CONSULTANTS 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100



CROSS SECTION OF CHECK DAM

	 10/10/2020	NAME OF WORK 10/10/2020	LEGEND 10/10/2020	DETACHMENT AREA 10/10/2020	WASTE NEAR 10/10/2020	TITLE 10/10/2020	DATE 10/10/2020	ENGINEERING CONSULTANT 10/10/2020	CLIENT 10/10/2020



WEEP HOLES LAYOUT

[illegible]